Work Orde <i>April-14-14 7:32</i>		358		*116358*								Page 1
Revision ID:	D3490-1 Cross Bolt Space	·r		Accept	*N900	040	100)*	Setup	Start Stop	*N	S1*
	4/14/14	" Start Qty: 180.00 Req'd Qty: 180.00	1 () ()		Cust Item I Customer:	D:				·	"IN	ラン ^
		MLS	•	Tooling: SPC (Y/N):		ate:			Run	Start Stop	"IV	R1* R2*
Sequence ID/ Work Center ID		Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	t Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revisio	on Nbr										
D3490	Rev A											
*1 \\A\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		FOLIO REV DWG REV:	S PER FOLIO FA628 & DW 7:	0.00 0.00 G D3490	:			DA 02 9-8:		H	14-	04-14 (4
*110 *110* QC Quality Control	Q	C2- Inspect parts off m	nachine FAI/FAIB	0.00				DAS 02 9-89	_ 4 1		14-0	4-14
120 *1 > 1 > 	Q	PC8- Inspect parts - seco	ond check	0.00 DAS 44 0.00 9-89	14/04/14			198		Ø		

Work Orde		6358		*116358*							age 2
Item ID: Revision ID: Item Name:	D3490-1 Cross Bolt Spa	acer	A	Accept	*N900	04010	// *	Setup	Start Stop	*NS1 *NS2	
Start Date: Required Date: Reference:	4/14/14 4/25/14	Start Qty: 180.00 Req'd Qty: 180.00	*180* *180*	l .	Cust Item I Customer:	D:				14.32	
Approvals:	Process Pla	n:	Date:	Tooling: SPC (Y/N):		ate:	_	Run	Start Stop	*NR1	*
Sequence ID/ Work Center II 130 *120*)	Operation Description Identify as per dwg & Stoo	ck Location:	Set Up/ Run Hours 0.00	Tool ID	Tool # Plan Code	Accep Qty 198	Qty	.]	Reject Insp. Number Stam	ıp ^
Packaging Packaging			OSSBOLT SPACER WITH I	0.00 ALUMINUM CLEANNE	CR.			/			•
140 *1 4 1 * * QC Quality Control		QC21- Final Inspection - \frac{1}{2}	Work Order Release	0.00			MU	5 19	1-01-	-15	
Quanty Control								A	14.	D4-15	

19.3

April-14-14 7:32:55 AM

Work Order ID: 116358

Parent Item:

D3490-1

116358 *D3490-1*

Parent Item Name: Cross Bolt Spacer

Start Date: 4/14/14

Required Date: 4/25/14

Start Qty: 180.00

Required Qty: 180.00

Comments:

IPP Rev:A New Issue 06-03-03 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M6061T6T0.500W.049		Purchased	No			100	f	85.0000	0.266	51			_
*M6061T6		W 049	t	1					** 02	AT.	14-	04-1	4

6061-16 KD Tube .500 x.049W

Location Loc Qty Loc Code MAT014 85 m126335 85

117270

DQA:	-	- Date:			WORK ORDER N	NON!	-CONFORMANCE / UPDATE					
QA Closed:		Date:			WORK ORDER I	VOIV-	CONF	JRIVIANCE / U	AEROSPACE			
W 10.1			DISPOSITION AGAINST DEPART					DEPARTMENT	/PROCESS	•		
Work Orde	r:				Davis			CLUM ALLE TO	<u>с</u> Г	_	\4/a4a# 1a4	7
Part N	0				Rewo Scra	-	ł	Skid-tube Machining	Crosstube Small Fab		Water Jet d. Eng. Coor.	Engineering Quality
raitiv	··				Use-as-	· 🛏	The	rmoforming	Finishing	_	re/Packaging	Other
NCR N	0.				Suspected Unapprove		1 '''	Large Fab	Composite	(Nec/310)	Supplier	
												
Root				Desci	ription of work order up	date	Initial	Ac	tion	Sign &		
Cause	Date	Step	Qty		or non-conformance	10	Chief Er	g Desc	cription	Date	Verification	QC Inspector
Design												
Doc/Data]											ļ
Equip/Tooling												
Handling/Pre												
Material												
Operator												
Offset/Setup												
Process			İ									
Supplier					ļ					ŀ		
Training		1										
Transport										İ		
Unapproved											<u> </u>	
						F	AULT C	ATEGORY				
Landin	g Gear			·	General	_			г	_	_	7
-	Bending			ļ	Bend	<u> </u>	_	/Program	<u> </u>	Outside Dim	<u> </u>	Pressure/Forced
-	Centre No	ot Concei	ntric	<u> </u>	BOM/Route		Grain		<u> </u>	Over/Under		Set-up
-	Cracks			<u> </u>	Broken/Damage/Defec	t	Hard		-	Part Incorre		Temperature/Cure
-	Crimp/Kir	nk/Ripple	:/Wave	\vdash	Burrs	,	-	ction Incomplete/U		Part Lost/Mi	_	Weld
-	Cuffs			<u> </u>	Contamination	-		ctions Incomplete/	'Unclear	Part Moved		Wrong Stock Pulled
}	Crushing			<u> </u>	Countersink		_	ligned/off center	-	Positioned V		ا ۔
}	Heat Trea			<u> </u>	Cut Too Short			beled	L	Power Loss/	Surge	Other
}	Inspectio	•	Tube	<u> </u>	Drawing		Misre					
}	Marks/Ch			\vdash	Drill Holes		Off-s					
. }	Turning S			<u> </u>	Finish	├	_	f Calibration				
	Wave/Tw	/ist in Tul	oe -	l	Fit/Function	\ I	[Out o	f Sequence				

H:/FORMS/Quality Assurance\approved QA/NCRWO RevH

DART AEROSPACE LTD	Work Order:	116358
Description: Crossbolt Spacer	Part Number:	D3490-1
Inspection Dwg: D3490 Rev: A		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments		
Ø0.500	+0.006/-0.001	0.499			ven	TT-4		
0.049	+/-0.010	0.017						
Ø0.402	+0.006/-0.001	0.405				·		
3.085	+0.030/-0.000	3.112						
0.050 x 45°	+/-0.010	0.042						
		-						
				,				


DAS

Measured by: 02
9-89
Date: 14-04-14
Date: 14/04/14
Date: 14/04/14
Date: 14/04/14
Date: 14/04/14
Date: 14/04/14

Rev	Date	Change	Revised by	Approved
Α	06.10.06	New Issue	KJ/JLM	
В	08.06.02	Dimensions and tolerances revised	KJ/DD 1.0	
С	08.10.07	0.050 x 45° dimension revised	KJ/DD	177



DESIG	PH	DRAWN BY	DART AEROSPACE USA,	INC.
CHECH	KED #	APPROVED	DRAWING NO. D3490 SHE	REV. A
DATE		1	TITLE	SCALE
06.0	1.04		CROSS BOLT SPACER	NTS
Α		06.01.04	NEW ISSUE	



D3490-1/-3/-5 CROSS BOLT SPACER PARTS LIST

PART NUMBER	OD	WALL	ID (REF)	MATERIAL SPEC
D3490-1	0.500	0.049	0.402	M6061T6T0.500W.049
D3490-3	0.750	0.080	0.591	M6061T6R0.750
D3490-5	0.313	0.058	0.197	M6061T6T0.313W.058

D3490-1/-3/-5 CROSS BOLT SPACER

- ALUMINUM 6061-T6 (QQ-A-200/8 OR QQ-A-225/8) 1) MATERIAL:
- 2) ALL DIMENSIONS ARE IN INCHES
- TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED



Copyright © 2006 by DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.